

Paul Osborne

Jus'Limin'

Carn Thomas

St. Mary's

Isles of Scilly

Heritage Impact Statement

The Galley Takeaway

The Parade, St. Mary's, Isles of Scilly.

THE GALLEY THE GALLEY RESTAURANT

1 contribution

Overview

Heritage Category:

Listed Building

Grade:

II

List Entry Number:

1141196

Date first listed:

14-Dec-1992

Statutory Address:

THE GALLEY RESTAURANT, THE PARADE

Statutory Address:

THE GALLEY, THE PARADE

Location

Statutory Address:

THE GALLEY RESTAURANT, THE PARADE

Statutory Address:

THE GALLEY, THE PARADE

The building or site itself may lie within the boundary of more than one authority.

District:

Isles of Scilly (Unitary Authority)

Parish:

St. Mary's

National Grid Reference:

SV 90296 10528

Details

ST. MARY'S

SV9010 THE PARADE, Hugh Town 1358-0/8/103 (South side) The Galley and The Galley Restaurant

GV II

House with shop attached. Early C19. Roughly coursed granite rubble with colour washed render to front; gabled slate and scantled slate roof; rendered end stacks. 2 storeys. The Galley to left, of one-window range, has C20 window above late C19 tripartite shop window with pilaster strips and frieze with cornice to architrave framing central C20 door flanked by two 6-light fixed casements. The Galley Restaurant to right is lower and of symmetrical 3-window range with unhorned 2/2-pane sashes and recessed C20 door. Interior: no features of interest noted. Included for group value.

Listing NGR: SV9029610528

PROPOSED WORKS

The proposed alteration to The Galley are to replace the front 6 pane windows and front door with window above.

The existing windows and door are beyond repair; the windows have become unstable and unsafe, the glazing moves within its frame, and the frames are weak and suffering from rot.

The main door has been made good year on year and is now at a stage that it has been repaired so many times it now requires replacement.

The applicant has sought the advise of the local carpenter to undertake the works to make good the repairs to the windows and door.

On inspection of the large 6 pane glass windows it has been established that these windows were not made by a qualified carpenter and most likely constructed using cheap materials that would have been handy at the time. This can be easily noted as the windows are fitted with window putty on both inside and out; this should be a wooden transom with a bead or putty fixing to the outside only.

This type of construction is a type of its time when health and safety was not a major consideration as it is these days.

The proposed replacement windows have been made to copy the existing listed windows to as close as they can be made whilst incorporating modern standards of build quality as possible.

The windows are on the side of a main highway with passing pedestrians continually knocking against the windows as they pass the building; it must also be noted that this area of highway is very restricted with occasional large vehicles mounting the pavement, this causes pedestrians to step back often leaning against the current unstable windows.

The replacement windows are identical in size to the existing windows, the original windows posts and door frame to remain. The only difference is the beading which will be made in the "Ovolo Moulding" traditional style, formed inside and out.

It is felt that the impact on the heritage of the listed building will not be affected. The existing window is a result of poor local construction. If the window frame had been constructed properly when the window was last replaced (this is not an original window), when the building gained its listing status the windows should have been of the proposed style.




Existing Windows/Door



Proposed Window Frame



Existing Beading



Proposed Colour Blue
To Replace White

Proposed Window
(Before Beading Attached)

