Existing front wooden single glazed windows and door.



Inside view of rotten windows frames.

