



Key



Internal view of garage showing vintage 'MG TA' convertible in good condition and running order



View of garage used for car parking with garage door open

Note boarded roof slope above rafters. There is no roofing felt and, on close inspection, water marks are visible showing current leaks



Recently installed kitchen showing commitment to retaining ground floor intact during extension work

Second view of kitchen showing new range

Internal view of attic. Note perimeter platform for railway track and old station

NOTES

- 1 THIS DRAWING IS THE COPYRIGHT OF THE ARCHITECT AND MAY NOT BE REPRODUCED WITHOUT LICENCE
- 2 ALL DIMENSIONS AND LEVELS ARE TO BE CHECKED ON SITE BY THE CONTRACTOR BEFORE COMMENCEMENT OF WORK AND ANY DISCREPANCIES REPORTED TO THE ARCHITECT
- 3 NO RESPONSIBILITY CAN BE ACCEPTED FOR ERRORS ARISING ON SITE DUE TO UNAUTHORISED VARIATIONS FROM THE ARCHITECT'S DRAWINGS.

AMENDMENTS

RECEIVED
By A King at 1:56 pm, Sep 01, 2023

PLANNING

Studio St Ives
4 Gabriel Street, St Ives
TR26 2LU
01736 798427

**MIKE BRADBURY
DESIGN**

JOB
Extension and Alterations to
Bishop View
Porth Loo Lane
St. Mary's
Isles of Scilly

TITLE
Existing Photographs

DRNG. NO. 2024-P08 **REVISION**

SCALE NTS **DATE** August 2023

OFFICE USE / PRE-ISSUE