

**PA/23/118** Photographs in support of planning application

Photo 1. View of the conservatory from upper E elevation of the property, facing W. The conservatory roof has a SE aspect and cannot be viewed from any properties from W through N to E and S.



Photo 2. A. View of the conservatory from Church Road, SW elevation. B. Zoomed in and cropped. The Guardian warm roof will blend far better with the weathered cedar shingle roof of the property and the reduced number of open windows will reduce the 'lattice' effect of the current conservatory frame.



Photo 3. View of the conservatory from E elevation facing W. The conservatory roof is in very poor condition.



Photo 4. View of the conservatory, NE elevation facing SW.



Photo 5. View of the conservatory, SW elevation facing NE. This is the side facing onto Church Road, Mundesley. Mature Tamarisk shrub at RHS of image.



Photo 6. Interior of conservatory, SW elevation facing NE. Leaking water has caused blistering to paintwork and damage to oak flooring, while an electrical socket is no longer working and is isolated.



Photo 7. Interior of conservatory, NE elevation facing SW. Granite rocks holding roof down visible in lower left corner.

