

Window No.	Location	Elevation/ Type		Comments
W001.	Dining Room			Existing single glazed sash window overhauled and retained. Localised timber repairs, sash cords replaced as necessary.
W002.	Entrance Porch	Existing 	Proposed 	Existing porch taken down and rebuilt. Replacement entrance door in original position of W002. Refer to Door Schedule.
W003.	Entrance Porch high level glazing	Existing 	Proposed 	New double glazed accoya fixed pane window. Profiles as per new entrance porch details.
W004.	Living Room			Existing single glazed sash window overhauled and retained. Localised timber repairs, sash cords replaced as necessary.
W005.	Bedroom 1			Existing single glazed sash window overhauled and retained. Localised timber repairs, sash cords replaced as necessary.
W006.	Landing			Existing single glazed sash window overhauled and retained. Localised timber repairs, sash cords replaced as necessary.
W007.	Bedroom 2 [Front]			Existing single glazed sash window overhauled and retained. Localised timber repairs, sash cords replaced as necessary.
W008.	Bedroom 2 [Side]			Existing single glazed sash window overhauled and retained. Localised timber repairs, sash cords replaced as necessary.
W009.	Snug	Existing 	Proposed 	New double glazed accoya timber sash as per window details.
W010.	Downstairs WC	Existing 	Proposed 	Existing stormproof window removed and opening enlarged back to its original door opening form. New double glazed door installed. Refer to Door Schedule.
W011.	Kitchen			Existing single glazed sash window overhauled and retained. Localised timber repairs, sash cords replaced as necessary.
W012.	Bedroom 3			Existing single glazed sash window overhauled and retained. Localised timber repairs, sash cords replaced as necessary.
W013.	Family Bathroom	Existing 	Proposed 	New double glazed accoya timber casement as per window details.

Window No.	Location	Elevation/ Type		Comments
W014.	Bedroom 4			Existing single glazed sash window overhauled and retained. Localised timber repairs, sash cords replaced as necessary.
W015.	Annexe Kitchen/ Shower Rm	Existing 	Proposed 	New double glazed accoya timber casement as per window details.
W016.	Annexe Bedroom	Existing 	Proposed 	New double glazed accoya timber casement as per window details.
W017.	Store [blocked up opening]	Blocked up opening		As existing retained.

Door No.	Location	Elevation/ Type		Comments
D001.	Main Entrance Porch	Existing 	Proposed 	Repositioned opening to D001A in new porch design. New timber 6 panel door with top two panels glazed.
D002.	Inner Porch/ Hallway Door	Existing 	Proposed 	New glazed timber door.
D003.	Dining Room			Existing retained
D004.	Living Room			Existing retained
D005.	Under Stairs Cupboard			Existing retained
D006.	Front hall to Back hall [door frame without door present]	Existing None	Proposed 	Salvaged from D008 opening [former downstairs WC]
D007.	Snug			Existing retained
D008.	Downstairs WC	Existing 	Proposed Removed. Salvaged door to D006	

Door No.	Location	Elevation/ Type		Comments
D009.	Kitchen	Existing 	Proposed Removed. Salvaged door set aside for reuse	
D010.	Kitchen/ Rear Porch	Existing 	Proposed 	New FLB timber door
D011.	Rear Porch to Outside	Existing 	Proposed Removed. Porch demolished.	
D012.	Bedroom 4			Existing retained
D013.	Family Bathroom			Existing retained
D014.	Bedroom 3			Existing retained
D015.	Bedroom 2			Existing retained
D016.	Bedroom 2 Ensuite	Existing 	Proposed Removed.	Existing is a 4 panel HDF board door.

Door No.	Location	Elevation/ Type		Comments
D017.	Bedroom 1			Existing retained
D018.	Annexe Kitchen/ Shower Room to outside			Existing retained with localised timber repairs
D019.	Annexe Bedroom			Existing retained
D020.	Store			Existing retained with localised timber repairs
D021.	Door from courtyard to rear [West] garden	Door frame but no door present.		
D022.	Door from courtyard to side [South] elevation garden.			Existing retained with localised timber repairs
D023.	Bedroom 1 - Built in cupboard [within original bedroom 4]	Existing None.	Proposed 	Pair of new timber 4 panel doors. Profiles to match existing.
D024.	Ensuite Shower Room [within original bedroom 4]	Existing None.	Proposed 	Pair of new timber 4 panel doors. Profiles to match existing.
W010.	Downstairs WC [part of proposed kitchen]	Existing 	Proposed 	New double glazed timber door to replace window opening.

RECEIVED

By Liv Rickman at 11:28 am, Sep 22, 2025


No. A
Date. Sept.25
Revision. Updated notes
Initial. IDR

NOTES.

© This drawing is copyright:-

Figured dimensions must be taken in preference to scaled dimensions.

Contractors, Sub-contractors and Suppliers must verify all dimensions on site before commencing work or perparing shop drawings.



DUCHY of
CORNWALL

WESTERN DISTRICT

Duchy of Cornwall
Restormel Estate Office
Lostwithiel
Cornwall PL22 0HN
01579 343149

DARTMOOR

Duchy of Cornwall
Princetown
Yelverton
Devon PL20 6QF
01822 890205

ISLES OF SCILLY

Duchy of Cornwall
St. Mary's
Isles of Scilly TR21 0LS
01720 422508

Manor

St Mary's

Project.

Veronica Lodge -
Refurbishment

Detail.

Window & Door
Schedule

Scale.

NTS

Drawing No.

MYS-VL-03

Revision No.

A

Drawn by.

IDR

Date.

March 2021