TREGARTHEN'S HOTEL. St MARY'S. ISLES OF SCILLY.

DEVELOPMENT OF A PAIR OF HOLIDAY COTTAGES WITHIN THE FORMER DERELICT GARDEN AND OTHER MINOR WORKS.

PLANNING REF. P/18/031/FUL

ADDENDUM TO DESISN AND PLANNING STATEMENT CONSIDERING FLOOD RISK MATTERS

J-545



TREGARTHEN'S HOTEL. St MARY'S. ISLES OF SCILLY.

DEVELOPMENT OF A PAIR OF HOLIDAY COTTAGES WITHIN THE FORMER DERELICT GARDEN AND OTHER MINOR WORKS.

PLANNING REF. P/18/031/FUL

ADDENDUM TO DESISN AND PLANNING STATEMENT CONSIDERING FLOOD RISK MATTERS

Report No.	Issue Detail	Originator	Date	Checked by	Date
J-545	01	TS	22/06/2018	EC	22/06/2018

For: Tregarthen's Hotel Ltd

Garrison Hill, Isles of Scilly St Mary's TR21 OPP **Job No:** J-545 **Date:** June 2018

Edition: 01

CONTENTS

Item	Content	Page No.
1.0	Introduction	1
2.0	Site Setting and Surrounding Conditions	1
3.0	Requirement for a Flood Risk Assessment	2
4.0	Wind and Wave Action	4
5.0	Flood Implications for Development	6
6.0	Risks Arising from Overtopping Water, Wind Driven Spray and Debris	8
7.0	Mitigation Measures	10
8.0	Conclusions	13

APPENDICES

Appendix A Environment Agency Letter of Objection Dated 06 June 2018

Appendix B Section Through Site Showing Sea Levels



1.0 INTRODUCTION

Tregarthen's Hotel Ltd. have submitted a planning application (P/18/031/FUL) for the development of a pair of holiday cottages within a derelict garden area of the Hotel, together with a series of other minor works to improve the operation and appearance of the hotel.

During the planning process, the application has received an objection from the Environment Agency (EA) on the grounds that the insufficient information has been submitted to demonstrate that the proposed development will be safe from flooding over its lifetime. A copy of the objection letter dated 6th June 2018 is attached within **Appendix A**.

This document is intended to address the perceived deficiencies in the information submitted with the planning application, as identified by the EA, thereby allowing them to lift their objection to the application. It relates to the element of the proposal to erect a pair of semi-detached dwellings in the derelict garden and does not cover other aspects of the application in higher areas of the site, as these are considered not to be relevant to the EA's objection.

2.0 SITE SETTING AND SURROUNDING CONDITIONS

The footprint of the proposed cottages is located towards the north west corner of the overall site of the Tregarthen's Hotel complex, in an area formerly used as gardens. The main part of the hotel building is situated close to the south of the proposed cottage development and there is an existing two storey building associated with the hotel, known as Hendra and Gibson to the immediate east. A residential plot is situated to the west.

The north boundary of the site faces onto a small tidal bay bounded by Rat island to the north and St Mary's Quay to the east; in the wider context this bay opens out into The Road, the area of sea between the islands of St Mary's and Tresco/Samson.

The development plot extends right down to the edge of the tidal waters where the rocky upper beach area is separated from the grounds of the hotel by means of vertical masonry faced sea wall. The level of the cope of the wall in this area is approximately 7.40m AOD whilst the ground level immediately inland of the wall is about 6.90m AOD. The typical ground level on the development plot varies from about 7.2m AOD to 9.8m AOD. The proposed finished floor level of the building is 7.85m AOD for the eastern unit and 8.80m AOD for the western unit.

The level on the rocky beach immediately seaward of the sea wall is about 2.85m AOD.



2.1 Sea Levels

Seawater levels in the bay will vary dependent upon the state of the tide and whether it is in neap or spring tidal cycle. Typical current day high water tide levels shown below in **Table 1**.

Tidal Event	Current Day Still Water Level (m AOD)	Still Water Level with Climate Change Allowance (m AOD)	
Highest Astronomical Tide	3.40	4.49	
Mean High Water Springs	2.77	3.86	
Mean High Water Neaps	1.44	2.53	
1 Year Return	2.81	3.90	
5 Year Return	3.30	4.39	
10 Year Return	3.43	4.52	
25 Year Return	3.49	4.58	
50 Year Return	3.59	4.68	
100 Year Return	3.75	4.84	
200 Year Return	3.82	4.91	

Table 1. Approximate Sea Levels – Current Day and with Climate Change Allowance

It is predicted that sea levels in the UK will be rising as a result of global climate change. Predictions provided by the EA recommend that an allowance of 1.09m should be assumed for net sea level rise in the south west of England over a 100-year horizon; 100 years is taken as a reasonable estimate for the lifetime of residential developments. As such, sea level may be assumed to rise by 1.09m over the lifetime of the development.

Predicted sea levels accounting for climate change over the lifetime of the development are also provided within **Table 1** in the right-hand column.

A section through the proposed development showing the relative level of the site compared to the principal still water tide levels is provided in **Appendix B**.

3.0 REQUIREMENT FOR A FLOOD RISK ASSESSMENT

With reference to **Table 1**, the extreme still water tidal event (1 in 200-year return period) when allowing for climate change is still significantly lower than the ground floor slab of the lowest proposed cottage, 4.91m AOD and 7.85m AOD respectively. This provides a freeboard of about 2.94m.

As such, based upon still water levels, and allowing for climate change, it may be concluded that the development is at negligible risk of flooding from tidal effects.

In this regard it is noted that Policy SS7 of the Council of the Isle of Scilly Draft Local Plan (extract provided below as **Figure 1**) does not ordinarily require Flood Risk Assessments (FRA) for coastal developments unless the level of the development is set at an elevation of 5m AOD or lower. This threshold is roughly consistent with the predicted 1 in 200 year still water tidal level allowing for climate change.



Policy SS7 does caveat that the need for an FRA is also influenced by whether the site is shown to be at risk from proposals maps; Figure 1 1 of the Local Plan Document. The resolution of Figure 1 1 is such that it is not possible to accurately identify the boundary of the site on the plan, so it is difficult to apply this requirement.

Reference has been made to the IoS Shoreline Management Plan 2 which is the source document for Figure 1. The Shoreline Management Plan (extract provided below as **Figure 2**) shows that the subject site is at risk of erosion if there is no active intervention to flood defences beyond 2055, though it does not necessarily identify that the site is at risk of flooding. It is relevant to note that the Shoreline Management Plan 2 (p30) recommends "Holding the Line" with respect to the existing sea defence wall outside the site. This objective is reinforced within the IoS Climate Change Strategy Plan (p39) which confirms that the quay wall by the Mermaid Inn is integral to the continued protection of the Hugh Town and it will be the Council's policy to maintain the line for sea defences in this area.

The conclusion is that the Council's policy does not necessarily require a Flood Risk Assessment for this site and that it is their intention to maintain the integrity of the existing seawall to the north of the site for the foreseeable lifetime of the development.




Figure 1. Policy SS7 Council of the Isle of Scilly Draft Local Plan






Figure 2. Extract from IoS Shoreline Management Plan 2 Showing Erosion Zones

4.0 WIND AND WAVE ACTION

The island of St Mary's is extremely exposed to Atlantic waves and swell particularly from westerly, southerly and easterly directions. The islands experienced severe storm conditions in February 2016 arising from storm Imogen, when wave heights off shore in the Atlantic were reported to be between 12m to 14m by the Met Office.

The section of quay wall directly outside of the Mermaid Inn, around 50m east of the site, faces almost due west and waves from this direction have almost unlimited fetch from across the Atlantic (see **Figure 3** below), though offshore wave heights will be significantly reduced by the shallow sea around the Islands.

The section of quay wall adjacent to the development site faces in a more northerly direction compared to the Mermaid Inn, and there is limited wave fetch from this direction as the extent of open sea is constricted by the islands of Samson, Tresco and St Martins to the north (**Figure 4**). As such, wave impact will be significantly worse on the west facing section of guay outside of the Mermaid Inn than at the subject site.

Large waves coming from a westerly direction will tend to propagate parallel to the sea wall at the site and impact on the wall opposite the Mermaid Inn, though refracted and reflected waves will also impact on the wall at the Tregarthen's. Waves arising from a northerly direction will impact directly on the wall at the development site, though waves form this direction will be of lower magnitude than waves form the west due to the reduced fetch across open water.



British Standard BS6349 for Maritime Works, section 23.5, notes than as a conservative estimate, the significant wave height (Hs) at a particular site may be taken as equal to 0.8 times the water depth at the site. Considering the 1 in 200 tidal event with climate change at the site, the still water level is predicted to be 4.91m AOD; the approximate beach level is 2.85m AOD therefore the significant wave height would be 1.65m. This is average trough to crest dimension for the highest third of the waves. As a rule of thumb, the highest 10% of waves would be 1.27 x Hs or 2.1m, and the highest 1% of the waves would be 1.67 x Hs or 2.8m.

This compares reasonably well with information provided within the Shoreline Management Plan for the Islands (p7) which predicts a 10% annual exceedance wave height of around 3.0m to 3.5m for St Mary's, though it is not certain if this is an inshore or off shore wave height prediction.

Overall an assessment of 2.8m for a large wave height at the site would seem to be reasonable. This is a trough to crest height, so the level of the crest of the wave would be one half of the overall wave height above the still water level. In the case of the 1 in 200-year tidal event with climate change, then the elevation of the wave crest height would be 6.31m AOD.



Figure 3. Plan Showing Fetch Direction Towards Mermaid Inn






Figure 4. Plan Showing Fetch Direction Towards Quay Adjacent to the Site

5.0 FLOOD IMPLICATIONS FOR DEVELOPMENT

Comparison of predicted tide level with allowance for climate change, and wave height, indicates a wave crest level at the site of 6.31m AOD compared to a cope level of the sea wall at 7.40m AOD and a ground level behind the wall of about 6.6m AOD. The ground then rises us to the location of the lower cottage unit where the proposed ground floor level is 7.85m AOD.

As such, the proposed building is protected by the seawall from direct impact by waves and the proposed slab level is in any event set about 1.5m above the crest level of the waves. Therefore, direct flooding of the



development by tide and wave action is not a realistic probability. However, with the effects of a strong northerly wind it is likely that wind driven spray and debris entrained within the water such as kelp and small beach pebbles could impact on the northerly gable end of the proposed building, given that it is set back only some 10m from the seawall. Water could also be lifted over the wall by the momentum of waves impacting with the wall, driving the wave crest up and over the cope of the wall.

Spray and debris could also impact upon the external areas between the adjacent car park and the cottages, which forms the proposed pedestrian access and egress route into the development.

It is recognised that inundation of this nature occurred during storm Imogen when water overtopped the sea wall outside of the Mermaid Inn and impacted on the external elevations of the building. Debris such as kelp and beach material were deposited on the roadway outside of the pub indicating that it had been picked up and entrained within the overtopping water.

Record photographs (**Figures 5 & 6**) show windblown spray almost up to the level of the ridge of the Inn building, approximately 11.0m AOD. Vehicles parked outside the pub were also damaged.



Figure 5. Wave Conditions Outside of Mermaid Inn During Storm Imogen





Figure 6. Wave Conditions Outside of Mermaid Inn During Storm Imogen

The effect of the storm on the site at the Tregarthen's Hotel is not known, but it was likely to be less severe than conditions experienced at the Mermaid Inn for a number of reasons. Firstly, the cope level of the sea wall opposite the Mermaid is set at a level of about 6.14m AOD whilst the comparable level opposite the development site is about 7.2m AOD. The ground levels behind the walls are 5.4m AOD and 6.6m AOD respectively and the Mermaid Inn is set back from the sea by only about 6m to 7m whilst the proposed cottages are set back at least 9.5m AOD. So, the defences to the Tregarthen's site are about 1m higher and the proposed building is set back further from the sea than the Mermaid Inn.

Of further note is the fact that the Mermaid Inn and the adjacent seawall face west towards the direction of the Atlantic fetch whilst the seawall protecting the subject site is aligned facing north, parallel to the direction of the greatest ocean swell; also, is afforded some protection by the headland to the west.

Therefore, though it is acknowledged that though there is a risk of overtopping water, spray and entrained debris impacting on the development site, conditions will not be as severe as those experienced at the Mermaid Inn. In this regard, it is relevant to note that there is no known record of damage to the existing Hendra Cottage which is located in the grounds of the hotel at a slightly lower elevation and similar distance to the sea wall than the proposed cottages.

6.0 HAZARDS ARISING FROM OVERTOPPING WATER, WIND DRIVEN SPRAY AND DEBRIS

Hazards arising from wind driven spray and debris projected over the seawall adjacent to the proposed development are as follows:

- Injury to persons
 - o Injury from kelp and beach debris projectiles when walking behind the seawall and lower garden area
 - o Injury to persons being knocked off their feet from water impact/wind force when walking behind the seawall and lower garden
 - o Injury from windows shattering within the proposed building



- Injury to persons being swept off their feet by fast moving water flowing back to the sea regarded to be low risk as volumes of water actually deposited behind the seawall will be relatively small
- Damage to property
 - Damage to windows on the seaward facing elevations of the proposed building
 - o Damage to vehicles parked between the cottages and the sea, broken windows, damaged body panels etc.

The risks from significant volumes of water entering the proposed building/flooding of the building are considered to be very low given the raised elevation and lateral separation of the building from the seawall and limited amount of "green" water that will actually overtop the wall. The ground profile falls back towards the sea from the proposed building at a relatively steep gradient of about 1 in 11, so overtopping water should run back to the wall fairly quickly and not move towards the building once it impacts on the ground.



Figure 7. Seaward Facing Elevation of Cottages Showing Window and Door Apertures

The closest seaward facing wall of the proposed building has no openings at ground level with only a single window opening at first floor level (**Figure 7**). The only seaward facing doorway is on the furthest elevation from the seawall at a separation distance of about 14m from the seawall and a threshold level of 8.80m AOD. This arrangement will protect against the risk of windblown spray entering through ground level apertures in the walls of the building.

Periods of High Risk

The risk of occurrence of windblown overtopping water/debris will be most significant during a spring tide cycle when the height of the tide will be at its greatest over a bi-weekly cycle. Spring tides occur twice every month during new and full moon conditions with the largest tides occurring a day or two after the full or new moon. The range of the spring tide is further increased around the equinoxes at spring (typically the 20th March) and autumn (typically the 22nd September).



Spring tides occur on a consistent bi-weekly basis with the peak of the tide typically occurring between 5:00 to 7:00 in the morning and 17:00 to 19:00 in the evening.

High spring tides are predictable, but weather conditions can create storm surges and ground swell that add to the water levels, so unfavourable conditions could still occur outside of the spring tide cycle, though the worst conditions will always occur during the coincidence of a high spring tide, strong winds from the north to north west and storm surge caused by low barometric pressure.

It is difficult to predict the exact combination of tide/weather conditions that may result in a risk of injury/damage from windblown overtopping water/debris, but it is suggested that the following weather/tidal conditions are taken as an indicator of potential dangerous conditions occurring;



Amber Alert - Significant overtopping is possible.

Seawater Level Predicted to exceed 2.7m AOD and wind predicted to approach Force 7 (high wind) from a northerly or westerly direction



Warning - Significant overtopping is expected.

Seawater Level Predicted to exceed 2.85m AOD and wind predicted to approach Force 8 (gale) from a northerly or westerly direction



Severe - Dangerous level of overtopping is expected

Seawater Level Predicted to exceed 3.0m AOD and wind predicted to approach Force 9 (severe gale) from a northerly or westerly direction

These threshold levels may be modified with ongoing experience of weather/tidal events and corresponding overtopping conditions at the site, though they are considered to be a safe and pragmatic starting point.

7.0 MITIGATION MEASURES

The following measures are proposed to mitigate against the risks of wind blown overtopping water and debris.

Mitigation Measures Through Design:

- Specify toughened glass in all seaward (north) facing doors and windows complying to Class 1 (C) when tested to BS EN 12600 for pendulum body impact resistance. (Pilkington T Glass or equivalent)
- Specify enhanced weathertight seals to all seaward (north) facing doors and windows
- Specify the installation of robust shutters to all windows on the seaward (north) facing elevation on the building



• Ensure that windborne water impacting of the front elevations of the building and garden area has a free drainage route back to the sea with adequate falls away from the building. This requirement is met by the existing design which provides patio areas and hard surfaced footways falling towards the seawall providing a drainage route away from the building. Landscape areas are also shown to be sloping away from the cottages back to the seawall. As such, no additional drainage measures are considered to be necessary.

It is noted that the cope level of the seawall is some 0.45m lower than the proposed lowest floor slab, so even in the unlikely event that all the drainage holes through the wall become blocked, any retained water can weir back over the wall into the sea without reaching the level of the habitable accommodation.

Provide an alternative means of access and egress through the hotel to the cottages which avoids
having to move through the lower part of the garden and the area immediately behind the sea wall.
Keep this route assessable at all times and clearly signed. The current proposed layout for the
development provides such an egress/access route as shown below in Figure 8.

Alternative access is available from the lower cottage to the main hotel around the west gable end of the cottage block at a minimum elevation of 7.85m AOD, whilst access for the higher cottage is available more directly via a doorway in the (south) back elevation of the building.




Figure 8. Plan Showing Alternative Access Egress Route in Event of Wave Overtopping Engineering and Development Solutions Ltd

Registered Office: Engineering and Development Solutions, Unit 10 Penstraze Business Centre, Truro, Cornwall, TR4 8PN
Registered in England and Wales No. 10467487
Phone 01872 306311 Mobile 07973816457



Operational Mitigation Measures:

- Develop a Flood Contingency Plan describing how the cottages will be operated and the residents managed when significant overtopping is expected. As a minimum this should address the following items:
 - Describe how weather and sea conditions will be monitored and when action will be triggered; refer to the suggested wind/tide threshold levels provided in **Section 6.0**. The plan should include proposals for monitoring local radio, monitoring the EA's website and keeping in contact with the IoS Council. In this regard the IoS Local Flood Risk Management Strategy notes that flood warning information will be disseminated by the Council by the following means:
 - Council website.
 - Community Message Board.
 - Tourist Information Office.
 - Town Hall.
 - Radio Scilly.
 - Posters in various locations.
 - Where deemed appropriate door knocking in specific vulnerable areas.
 - Direct to IOS Fire and Rescue Service.
 - General flooding advice is provided on the Council website and Z-Cards have been produced and distributed to all households giving information about how to be prepared in the event of an emergency including flood incidents



Amber Alert - Significant overtopping is possible.

- Monitor flood warnings and advice issued by the Environment Agency, IoS Council, the Emergency Services and local radio
- Monitor sea conditions at the seawall
- Prepare to implement Flood Contingency Plan



Warning - Significant overtopping is expected.

- Continue to monitor flood warnings and weather/tide conditions
- Put Flood Contingency Plan into action
- Inform affected guests that flood contingency plan is in force



Severe - Dangerous level of overtopping is expected

- Continue to monitor flood warnings and weather/tide conditions
- Continue to enforce Flood Contingency Plan and monitor effectiveness
- Advice guests when tide/weather conditions have subsided to safe levels and that normal operation is resumed
- Advise guests of likelihood of Flood Contingency Plan being implemented again during next tidal cycle



- Describe proposals as to how guests will be informed about overtopping risks, mitigation measures and alternative access routes when first checking into the hotel
- o Describe how guests will be informed about the requirements of the Flood Contingency Plan and how they will be informed when the Plan is in place.
- o Describe the alternative access/egress route to the cottage and explain how this will be kept clear and available for use by guests at all time when the Flood Contingency Plan is in force
- Describe how any vehicle associated with the cottage will be moved to higher ground if parked in the lower parking area
- Describe how shutters will be deployed to windows
- Describe how the normal access route to the lower garden/seawall area will be locked off or signed to prohibit access in this direction
- Describe how the risks will be deemed to have subsided to normal levels and how this will be communicated to guests
- Register with the Environment Agency's countrywide flood warning system in as far as it covers the Isle
 of Scilly. Flood warnings are issued by phone, text or email. Registration to receive warnings can either
 be by phone on 0345 988 1188 or online at www.gov.uk/sign-up-for-flood-warnings

Provided that the specified mitigation and contingency measures are adopted, then it is considered that the development may be operated in a safe and appropriate manner over its lifetime.

8.0 CONCLUSIONS

The proposed development at Tregarthen's Hotel comprises the construction of two new cottages within a distance of some 10m of the sea. The buildings are protected to the seaward side by an existing sea wall and raised ground. It is the intention of the Isles of Scilly Council to maintain the sea defences in this area as part of their Shoreline Management Plan and Climate Chane Strategy, so the buildings will benefit from these defences over their lifetime.

The floor level of the lowest area of the cottages is proposed to be set at a level of 7.85m AOD. The maximum still seawater level adjacent to the development, allowing for the effects of climate change over the next 100 years, is predicted to be 4.91m AOD with a wave crest levels of about 6.31m AOD. Therefore, the proposed development is not considered to be at risk of direct tidal flooding. This conclusion is supported by Policy SS7 of the Council of the Isle of Scilly Draft Local Plan which states that coastal developments will not ordinarily require a Flood Risk Assessments unless the level of the development is set at 5m AOD or lower.

Notwithstanding this, is it recognised that windblown overtopping water and entrained debris may impact upon the site during periods of high tide and unfavourable wind conditions, and that this may present risks to property and guests using the cottages.

The nearby Mermaid Inn and quay area have a history of serious windblown and wave overtopping water, most recently during Storm Imogen which occurred in February 2016. However, it is considered that conditions observed at the Mermaid Inn are not directly comparable to the development site as it does not face in the worst direction of open sea fetch and large waves/swell will tend to propagate parallel to the site rather than directly at it. In addition, the elevation of the sea defences and ground behind at the site are at least 1m higher than respective levels at the Mermaid Inn.

J-545 Addendum to Design and Planning Statement. Tregarthen's Hotel. IoS



To mitigate risks to acceptable levels, it is recommended that some minor items are implemented within the design of the development, some of which are already inherently met within the existing design. In summary, these are as follows;

- Toughened glass and enhanced weathertight seals in all seaward (north) facing doors and windows
- Robust shutters to all windows on the seaward (north) facing elevation on the building
- Free drainage route with adequate fall to all interrupted runoff of windblown water back to the sea
- Provide an alternative means of access and egress which avoids having to move through the lower part of the garden and the area immediately behind the sea wall.

It is further recommended that a Flood Contingency Plan is prepared describing how the cottages will be operated, and the residents managed when significant overtopping is expected. Requirements for the content of the Flood Contingency Plan are provided within **Section 7.0** of this report.

Provided that the specified mitigation and contingency measures are adopted, then it is considered that the development may be operated in a safe and appropriate manner over its lifetime.

APPENDIX A EA Letter of Objection

Ms Lisa Jackson
Jackson Planning Ltd
Fox Cottage Hatchett Hill
Lower Chute
ANDOVER
SP11 9DU

Our ref: DC/2018/119775/01-L01

Your ref:

Date: 06 June 2018

Dear Ms Jackson

REVISED SCHEME FOR REDEVELOPMENT OF TREGARTHENS HOTEL INCLUDING (1) ERECTION OF A PAIR OF SEMI-DETACHED DWELLINGS FOR RESTRICTED HOLIDAY LETTING (USE CLASS C3) INCLUDING ASSOCIATED LANDSCAPING. (2) ALTERATIONS TO EXTERNAL FACADE OF HOTEL LOUNGE AND HOTEL BEDROOMS INCLUDING REPLACEMENT WINDOWS/DOORS. FORMATION OF NEW WINDOWS AND REMOVAL OF EXISTING CHIMNEY. (3) FORMATION OF A NEW PEDESTRIAN OPENING IN THE EXISTING WALL ADJACENT TO GARRISON HILL. (4) FORMATION OF EXTERNAL SEATING AREAS AND NEW BALUSTRADES TO HOTEL ROOMS AND HOTEL LOUNGE. (5) INSTALLATION OF GROUND SOURCE HEAT PUMP/LOOP, BREAK TANK FOR FOUL SEWAGE. (6) REPLACEMENT FLAGPOLE. (7) DOWNLIGHTS ON EXISTING LETTERING ON FRONT OF MAIN HOTEL BLOCK. (8) DOWNLIGHTS AND NEW EXTERNAL LETTERING ON REAR OF MAIN HOTEL BLOCK. (9) ADDITIONAL LIGHTING TO WALL ON GARRISON HILL (HOTEL EXTERNAL TREGARTHEN'S HOTEL, GARRISON HILL, HUGH TOWN, ST MARY'S, TR21 0PP

The Environment Agency has recently been consulted by the Local Authority regarding the above development proposal. Please find enclosed a copy of our comments for your information.

This response represents our advice as a statutory consultee on environmental issues associated with the proposed development. The reply should not be confused with the Council's decision notice, which will be issued by the Local Authority following determination of the application. Please contact the Local Authority if you wish to discuss the final decision to be made on this application.

If you have any queries about the Agency's response, please don't hesitate to contact me.

Yours sincerely

Environment Agency
Manley House Kestrel Way, Sowton Industrial Estate, Exeter, EX2 7LQ.
Customer services line: 03708 506 506
www.gov.uk/environment-agency
Cont/d..

Miss Harriet Fuller Planning Advisor

Direct dial 02030256485 Direct fax 07785 601 798 Direct e-mail spdc@environment-agency.gov.uk

End 2

Ms Lisa Walton
Council of the Isles of Scilly
Planning & Development Department
Old Wesleyan Chapel Garrison Lane
St Mary's
Isles of Scilly
TR21 0JD

Our ref: DC/2018/119775/01-L01

Your ref: P/18/031/FUL

Date: 06 June 2018

Dear Ms Walton,

REVISED SCHEME FOR REDEVELOPMENT OF TREGARTHENS HOTEL INCLUDING (1) ERECTION OF A PAIR OF SEMI-DETACHED DWELLINGS FOR RESTRICTED HOLIDAY LETTING (USE CLASS C3) INCLUDING ASSOCIATED LANDSCAPING. (2) ALTERATIONS TO EXTERNAL FACADE OF HOTEL LOUNGE AND HOTEL BEDROOMS INCLUDING REPLACEMENT WINDOWS/DOORS, FORMATION OF NEW WINDOWS AND REMOVAL OF EXISTING CHIMNEY. (3) FORMATION OF A NEW PEDESTRIAN OPENING IN THE EXISTING WALL ADJACENT TO GARRISON HILL. (4) FORMATION OF EXTERNAL SEATING AREAS AND NEW BALUSTRADES TO HOTEL ROOMS AND HOTEL LOUNGE. (5) INSTALLATION OF GROUND SOURCE HEAT PUMP/LOOP, BREAK TANK FOR FOUL SEWAGE. (6) REPLACEMENT FLAGPOLE. (7) DOWNLIGHTS ON EXISTING LETTERING ON FRONT OF MAIN HOTEL BLOCK. (8) DOWNLIGHTS AND NEW EXTERNAL LETTERING ON REAR OF MAIN HOTEL BLOCK. (9) ADDITIONAL EXTERNAL LIGHTING TO WALL ON GARRISON HILL (HOTEL SIDE). TREGARTHEN'S HOTEL, GARRISON HILL, HUGH TOWN, ST MARY'S, TR21 0PP

Thank you for consulting us on this planning application.

Environment Agency position

We object to the proposed development on the grounds that insufficient information has been submitted to demonstrate that the proposed development will be safe from flooding over its lifetime. The application should not be determined until further evidence has been submitted to show that the risk of tidal flooding has been satisfactorily addressed.

The reasons for this position are set out below.

Reason-Flood risk

The development site is adjacent to the Mermaid Wall sea defences which are known to be subject to frequent overtopping by waves during storm events. Flood risk mapping currently being prepared for St Mary's indicates that the area referred to as 'derelict kitchen gardens', and which is earmarked for the construction of residential

Environment Agency

Manley House Kestrel Way, Sowton Industrial Estate, Exeter, EX2 7LQ.

Customer services line: 03708 506 506 www.gov.uk/environment-agency

Cont/d..

'cottage' dwellings, is likely to be subject to flooding from the sea along its northern half during extreme storm events, this includes the car parking area and the existing 'Hendra' cottage.

The primary risk is from wave overtopping and wind driven spray resulting in the area becoming hazardous for pedestrians during extreme storm events due to the 1) Velocity and volume of wind-driven spray and 2) Projectiles and debris propelled by the overtopping waves.

It also needs to be considered that wave overtopping events are likely to become more severe and more frequent over time, due to the effects of climate change and sea level rise.

The submitted Planning & Design Statement does not reference flood risk from the sea. It should be acknowledged that currently no published flood risk zones exist for the Isles of Scilly and therefore the oversight may be due to this technicality. However, wave overtopping in the vicinity of the Mermaid Wall is well documented and the applicant needs to acknowledge this issue of flood risk from the sea during extreme storm events and provide evidence as to how it has been considered. This includes in terms of safety and wellbeing of any guests, or staff who might be exposed to those conditions whilst staying or working in or around the proposed new garden cottages. Details of current sea defences and access arrangements associated with that part of the hotel grounds will also need to be considered.

Overcoming our objection

Further documentation needs to be submitted that demonstrates that:

- a) The risk is acknowledged and all aspects of it are discussed in the Planning and Design Statement.
- b) Design documentation identifies how the cottages and associated drainage systems would cope with, and be resilient to, the effects of such wave overtopping/flooding, including allowance for wave overtopping becoming more severe and more frequent over time, due to the effects of climate change and sea level rise.

Production of the described evidence will not in itself result in the removal of an objection.

Please contact us again if you require any further advice.

Yours sincerely


Harriet Fuller Planning Advisor

Direct dial 02030256485
Direct e-mail spdc@environment-agency.gov.uk

cc Jackson Planning Ltd

End 2

APPENDIX B Section Through Site Showing Water Levels



Copyright - This drawing and any ancillary drawings or data are copyright of EDS and may not be used, copied or amended for any purpose whatsoever without written approval.

NOTES

- 1. This drawing is copyright. Refer to details above.
- 2. This drawing is only to be used for the purposes described in the status box below. Work to figured dimensions only, do not scale.
- . This drawing is to be read in conjunction with all other drawings, details and specifications pertaining to the work
- Materials and workmanship shall comply to the appropriate British Standards and Codes of Practice unless otherwise
- . The activities required to construct the work, shown on drawings clearly marked FOR CONSTRUCTION, may be subject to the provisions of the Construction (Design & Management) Regulations 2015. The Contractor and Client must ensure that they are adequately conversant with these regulations and that the appropriate procedures required under the regulations are observed at all times.
- 6. Design Risk Assessment
- A risk assessment relating to potential hazards associated with the construction, operation and demolition of the work described within this drawing, in so far as it has been designed by EDS, has been undertaken. Risks so identified have been eliminated by design wherever practicable. The situation with regard to residual risks is as follows:

Planning stage – to be risk assessed at detail design stage.

22:06:18	TPS	EC	А	REPORT ISSUE		
DATE.	DRWN.	CHKD.	REV.	NOTES.		
PROJECT MANAGER:-				JAN CLARK		
PROJECT ENGINEER:-				TIM SULLIVAN		
DRAWN DATE:-				JUNE 2018		
SCALE & SHEET SIZE:-				1:80 @ A1		

PRELIMINARY



EDS, Unit 10, Penstraze Business Centre, Truro, Cornwall TR4 8PN (01872) 306311 (Mob) 07973816457 Email: jan@eadsolutions.co.uk www.eadsolutions.co.uk

TREGARTHEN'S HOTEL LTD

DEVELOPMENT OF A PAIR OF COTTAGES ADDENDUM TO DESIGN AND PLANNING STATEMENT

DRAWING TITLE

SECTION THOROUGH SITE SHOWING TIDE AND WAVE LEVELS

PROJECT No. DRAWING No. J-545 3000



Engineering and Development Solutions Ltd
Registered Office: Unit 10 | Penstraze Business Centre | Truro | Cornwall | TR4 8PN
Registered in England No. 10467487