

Heritage Statement for proposed alterations to the listed building at Lloyds Bank, St Mary's Isles of Scilly TR21 0PW, to remove external signage and an external ATM.



Google Maps view

The description from the Listed Building Register is:

Heritage Category: Listed Building
Grade: II
List Entry Number: 1141218
Date first listed: 14-Dec-1992
Statutory Address 1: LLOYDS BANK, HUGH STREET

Location

Statutory Address: LLOYDS BANK, HUGH STREET

The building or site itself may lie within the boundary of more than one authority.

District: Isles of Scilly (Unitary Authority)

Parish: St Mary's

National Grid Reference: SV 90181 10605

Details

ST MARY'S

SV9010 HUGH STREET, Hugh Town 1358-0/8/60 (South Westside) Lloyds Bank

GVII

House, now bank. Mid C19. Colourwashed render over granite rubble; gabled scantled slate roof; rendered end stacks. Double-depth plan. 2 storeys; 4-window first-floor range. Horned 2/2-pane sashes. Porch to left of centre. With 2 Roman Doric columns and correct Doric antae, entablature and cornice; 4-panelled door and rectangular fanlight. Interior: enriched cornices to ground floor. Included for group value.

Listing NGR: NGRmSV9018110605

Legacy

The contents of this record have been generated from a legacy data system

Legacy System number: 172195

Legacy System: LBS

The branch is to close and therefore the signage and ATM are to be removed.

On the front elevation, a set of individual letters fascia sign, a hanging projecting sign and bracket and a branch address plaque are to be removed and the redundant fixing holes are to be filled with lime mortar to match the existing render as closely as possible. A logo sign is to be removed from the fanlight above the entrance door. The external ATM is to be removed. The infill-to-window walling around the ATM is to be removed. The section of window above the ATM is to be removed. A new timber-framed sash window is to be installed to match the style of the windows to the right of the entrance. The night safe on the side elevation is to be retained to show the heritage of the property. The night safe will be temporarily fixed shut. The Lloyds Bank decal on the night safe will be removed.

These proposed alterations are not considered to detract from the listed building appearance, character, and quality.

Lime mortar will be natural hydraulic lime (3.5) with a fine-sieved, natural crushed-stone aggregate, mixed in the ratio of 1 part lime : 3 parts aggregate, tinted to match the colour of the brickwork as closely as possible when filling redundant holes and to match the existing mortar for the pointing.