

Tregarthen's Hotel
Site Waste Management Plan

Date Revision

Estimated Waste

Waste stream	Waste totals (tonnes)							Total	Comments
	Disposed - land-fill	Disposed - other	Recycled - recycling facility	Recycled - used off-site	Recycled - used on-site	Reused - off-site	Reused - on-site		
Units 1 to 8:									
Top Soil								0.00	
Excavated Material								0.00	
Concrete in excavations					4.00			4.00	
Masonry in walls & partitions					40.00			40.00	
Wood	2.83							2.83	
Plasterboard	0.71							0.71	
Bituminous Felt	0.78								
General waste (rubbish)	8.00							8.00	
Reception Entrance:									
Masonry in walls & partitions					9.00			9.00	
Wood	0.25							0.25	
Plasterboard	0.10							0.10	
General waste (rubbish)	0.50							0.50	
Dining Room Alterations:									
Masonry in walls & partitions					4.32				
General waste (rubbish)	0.50								
Staff Accomodation:									
Masonry in walls & partitions					5.76			5.76	
General waste (rubbish)	0.10								
								0.00	
Total (t)	13.77	0.00	0.00	0.00	63.08	0.00	0.00	71.15	
Total (%)	19%	0%	0%	0%	89%	0%	0%	100%	

Notes

Tregarthen's Hotel
Site Waste Management Plan

Date

Revision

Waste movements

No.	Waste producer	Waste stream	Material type	Further description of waste	On or off-site destination	Off-site carrier	Destination	Date of movement	quantity (no.)	weight (t)	total (t)	Actual Cost	£/m3	£/t
1	All	Non Hazardous	General Waste		Recycled - recycling facility									
2	All													
3	All													
4	All													
5	All													
6	All													
7	All													
8	All													
9	All													
10	All													
11	All													
12	All													
13	All													
14	All													
15	All													
16	All													
264														
Insert rows above														

Waste producer	Waste stream
ALL	Non Hazardous

Destination type
Reused - on-site
Reused - off-site
Recycled - used on-site
Recycled - used off-site
Recycled - recycling facility
Disposed - land-fill
Disposed - other